28 DEC 1983

## REAL ESTATE AND CONSTRUCTION DIVISION WEEKLY REPORT FOR PERIOD ENDING 28 DECEMBER 1983

	1.	Progress Report Tasks Assigned by the DCI/DDCI:
STAT		None
	2.	Items or Events of Major Interest that Have Occurred During the Preceding Week:
	line enti	Map Library - On 26 December, 1983, two water s burst due to freezing and caused considerable damage to the re Map Library area.
	as a carp	One water sprinkler line burst outside the leased area and result the water flowed into the library area and wet the et and caused some minor partition damage.
STAT	in c	Another pipe burst which is above the map net area. This water leaked through the ceiling which resulted eiling tile damage and created a water level of 3-4 inches on floor.
STAT	crew	Management did take immediate action by having a cleaning that worked all that night and part of the next day.
	carp	There is a work crew that is presently drying out the carpeting. d on the D/L's suggestion, it is possible to dry out the eting under the large map cabinets by removing one or two r drawers.
	drie	Since most of the telephone conduits and outlets have been d out, most of the employees are back at work.
STAT STAT	a fl	Another major problem that requires further investigation is oor slab that has receded approximately two inches.
	3.	Significant Events Anticipated During the Coming Week:
		None
STAT		